Re: Unit 1760 - Phase 2 - Omega Villas

Jay Pietrafetta <jayp@sunrisemgtfl.com>

Wed, Feb 21, 2024 at 8:36 AM

To: "Shawn Martin" <smartin@isccompany.net>, "Dorin Frai" <dfrai@yahoo.com>, "Omid John" <esq@omidjohn.com>

Cc: <austrolevy@gmail.com>, <daniel@s-deng.com>

He installed the WRONG patch. He installed a patch that would go on a high rise parapet wall roof, not a TPO flat roof. That patch is the Reason for your leaks!

When an oil based product is added to a TPO flat roof it deteriorates the surface of the membrane; it also doesn't adhere properly to the TPO membrane (just like the big patch he installed over the weekend (it is peeling off and created a huge water bubble that is trapping water in between the layers). You can check for yourself, but the guy was a hack.

You need permission to do any work on your roof from the Association so we can have the proper fix done. You emailed yesterday at 9:47 and I responded by 9:55 and we were on your roof 45 mins later. The leak you have is CAUSED by the incorrect job that guy did you hired. The warranty is worth nothing; it is trapping water and eating away at our TPO membrane. We will be happy to meet you and go on the roof and show you what a horrible job he did. It is the WRONG PATCH.

Just giving you the facts...

JAY PIETRAFETTA

President



Sunrise Property Management is committed to providing superior Property Management Services to Residential Community Associations and Board.

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the system manager.

From: Shawn Martin <smartin@isccompany.net>

Sent: Wednesday, February 21, 2024 7:14 AM

To: Dorin Frai <dfrai@yahoo.com>; Omid John <esq@omidjohn.com>

Cc: Jay Pietrafetta <jayp@sunrisemgtfl.com>; Levy Horvath <austrolevy@gmail.com>; Daniel <daniel@s-deng.com>

Subject: Re: Unit 1760 - Phase 2 - Omega Villas