



1 – Ongoing, removal of the existing roofing cover material and damaged plywood, BLDG 6.



2 – Ongoing, replacement of damaged plywood, BLDG 6.



INSPECTION – ENGINEERING – CONSTRUCTION
QB# 52647 – COA# 28388

Property: Omega Villas Condominium Association
Location : 1713 NW 72 Avenue,
Plantation, FL 33313
Job No: S&D Project No. 19094

Site
Photos



3 – Ongoing, removal of the existing roofing cover material and damaged plywood, BLDG 6.v




4 – Ongoing, removal of the existing roofing cover material and damaged plywood, BLDG 6.



INSPECTION – ENGINEERING – CONSTRUCTION
QB# 52647 – COA# 28388

Property: Omega Villas Condominium Association
Location : 1713 NW 72 Avenue,
Plantation, FL 33313
Job No: S&D Project No. 19094

Site
Photos



5 – Ongoing, placement of the black paper on top of plywood, BLDG 6.



6 – Ongoing, placement of the black paper on top of plywood, BLDG 6.



INSPECTION – ENGINEERING – CONSTRUCTION
QB# 52647 – COA# 28388

Property: Omega Villas Condominium Association
Location : 1713 NW 72 Avenue,
Plantation, FL 33313
Job No: S&D Project No. 19094

Site
Photos



7 – Ongoing, replacement of existing damaged plywood, BLDG 13.



8 – Ongoing, replacement of existing damaged plywood, BLDG 13.





9 – Ongoing, replacement of existing damaged plywood, BLDG 13.



10 – Ongoing, replacement of existing damaged plywood, BLDG 13.



INSPECTION – ENGINEERING – CONSTRUCTION
QB# 52647 – COA# 28388

Property: Omega Villas Condominium Association
Location : 1713 NW 72 Avenue,
Plantation, FL 33313
Job No: S&D Project No. 19094

Site
Photos



11 – Ongoing, placement of the black paper on top of plywood, BLDG 13.



12 – Ongoing, placement of the black paper on top of plywood, BLDG 13.



INSPECTION – ENGINEERING – CONSTRUCTION
QB# 52647 – COA# 28388

Property: Omega Villas Condominium Association
Location : 1713 NW 72 Avenue,
Plantation, FL 33313
Job No: S&D Project No. 19094

Site
Photos