

Omega Villas Condominium Association

1713 NW 72 Avenue,
Plantation, FL 33313

Progress Report
(04/19/2024)





1 – Identification and marking of the delaminated stucco at exterior walls



2 – Ongoing, identification and marking of the delaminated stucco at exterior walls



3 – Removal of the wood siding around the window perimeters at the exterior walls



4 – Ongoing, Application of the new stucco at the exterior walls.



5 – Cutting and chipping of the delaminated and cracked stucco at the exterior walls.



6 – Cutting and chipping of the cracked stucco at the exterior walls.



7 – Ongoing, Application of the new stucco at the exterior walls.



8 - Ongoing, Application of the new stucco at the exterior walls.