

Omega Villas Condominium Association

1713 NW 72 Avenue,
Plantation, FL 33313

Progress Report (04/26/2024)





1 – Cutting and chipping of the delaminated and cracked stucco at the exterior walls.



2 – Ongoing, Application of the new stucco at the exterior walls, around the window's perimeter.





3 – Ongoing, Application of the bonding agent and the new stucco at exterior walls.



4 – Ongoing, Application of the bonding agent and the new stucco at exterior walls.





5 – Ongoing, Inspection of the new stucco at the exterior walls.



6 – Ongoing, Inspection of the new stucco at the exterior walls.





7 – Cutting and chipping of the delaminated and cracked stucco at the exterior walls.



8 – Ongoing, installation of the roof vent cover.





9 – Ongoing, Application of the new primer and paint at the exterior walls.



10 - Application of the new primer and paint at the exterior walls.



INSPECTION – ENGINEERING – CONSTRUCTION
QB# 52647 – COA# 28388

Property: Omega Villas Condominium Association
Location : 1713 NW 72 Avenue,
Plantation, FL 33313
Job No: S&D Project No. 19094

Site
Photos