

Omega Villas Condominium Association

1713 NW 72 Avenue,
Plantation, FL 33313

Progress Report
(05/10/2024)






1 – Application of the new stucco at the exterior walls, around the window's perimeter.



2 – Application of the new stucco at the exterior walls, around the window's perimeter.



3 – Ongoing, Cutting and chipping of the delaminated and cracked stucco at the exterior walls.




4 – Ongoing, Application of the bonding agent and the new stucco at exterior walls.



5 – Ongoing, Application of the new primer and paint at the exterior walls.



6 – Ongoing, Application of the new primer and paint at the exterior walls.



7 – Ongoing, Installation of the wood false ceiling at the back of the building.



8 – Installation of the wood false ceiling at the back of the building.



9 – Installation of the wood false ceiling at the back of the building.



10 - Application of the new primer and paint at the exterior walls.