

# Omega Villas Condominium Association

1713 NW 72 Avenue,  
Plantation, FL 33313

## Progress Report (05/03/2024)





1 – Application of the new stucco at the exterior walls, around the window's perimeter.



2 – Application of the new stucco at the exterior walls, around the window's perimeter.



INSPECTION – ENGINEERING – CONSTRUCTION  
QB# 52647 – COA# 28388

Property: Omega Villas Condominium Association  
Location : 1713 NW 72 Avenue,  
Plantation, FL 33313  
Job No: S&D Project No. 19094

Site  
Photos



3 – Ongoing, Cutting and chipping of the delaminated and cracked stucco at the exterior walls.



4 – Ongoing, Application of the bonding agent and the new stucco at exterior walls.





5 – Ongoing, Application of the bonding agent and the new stucco at exterior walls.



6 – Ongoing, Application of the bonding agent and the new stucco at exterior walls.





7 – Ongoing, Application of the filler material and caulking at exterior surfaces.



8 – Ongoing, Inspection of the old stucco at the exterior walls.





9 – Ongoing, Application of the new stucco at exterior walls.



10 - Application of the new primer and paint at the exterior walls.



INSPECTION – ENGINEERING – CONSTRUCTION  
QB# 52647 – COA# 28388

Property: Omega Villas Condominium Association  
Location : 1713 NW 72 Avenue,  
Plantation, FL 33313  
Job No: S&D Project No. 19094

Site  
Photos