

Omega Villas Condominium Association

1713 NW 72 Avenue,
Plantation, FL 33313

Progress Report
(05/31/2024)





1 – Ongoing, Chipping of the marked and deteriorated stucco on exterior walls.



2 – Ongoing, Application of the new stucco at the exterior walls, around the window's perimeter.



3 – Ongoing, Chipping of the marked and deteriorated stucco on exterior walls.



4 – Ongoing, Application of the new stucco at the exterior walls, around the window's perimeter.



5 – Ongoing, Application of the crack filler at at the ceiling



6 – Ongoing, Application of the primer layer on ceiling at the back of the building.



7 – Ongoing, Application of the new stucco at the exterior walls



8 – Ongoing, Installation of the wooden fence.



9 – Ongoing, Installation of the wooden fence.



10 - Application of the new primer and paint at the exterior walls.